

**SECRET**

NRO REVIEW COMPLETED

[REDACTED]

25X1

Copy 6 of 6

26 AUG 1963

MEMORANDUM FOR: AFIGO-S  
Headquarters USAF

ATTENTION : Colonel Leo P. Geary

SUBJECT : Rotor Assembly, P/R EB-4-6115-06025

1. As requested in your 1st Indorsement, dated 13 August 1963, the following details pertaining to the damage to subject Rotor Assembly are submitted.

a. On 25 March 1963 a Rotor Assembly for a turbocharger, Part No. 878N-6115-00-0215, Serial No. U-9118-5, Model L-604, Size 1L3-PBT-7313, Style "B", was ordered on Voucher No. 63-26052, Request No. 5654, for 1250 KW Generator No. 58038. This Rotor Assembly was received and installed on 1250 KW Generator No. 58038.

b. The Rotor Assembly removed from the Generator was turned in on 10 June 1963 on Voucher No. 63-37571, dated 10 June 1963, for overhaul and return [REDACTED] This Rotor Assembly was received as a used assembly with Generator No. 58038 from Minot, North Dakota, and had 6,000 running hours [REDACTED] before it was removed. Previous running time at Minot is unknown. The grind or balance marks on the blades were made by the Elliott Company in order to balance the assembly.

2. [REDACTED] statement in his letter of 30 July 1963 is misleading, as we are dealing with two separate Rotor Assemblies; and the warranty on the one sent in for rebuilding has expired. The Rotor Assembly purchased in May 1963

25X1

**SECRET**

[REDACTED]

**SECRET**

Page Two

(paragraph 1.a.) is presently installed and in use on Generator No. 58038 and was not returned for overhaul. The Rotor Assembly discussed in paragraph 1.b. above was the one returned.

FOR THE DEPUTY DIRECTOR (SCIENCE AND TECHNOLOGY)

BY: (Signed)   
 *pc* JACK C. LEDFORD  
 Colonel USAF

MD/OSA (23 Aug 63)

Distribution: Copy 1 - AFIGO-S  
2 - AD/OSA  
3 - D/FA/OSA  
4 - MD/OSA  
5 - Chrono  
✓6 - RB/OSA

**SECRET**